

NATIONAL  
TRANSPORTATION  
SAFETY  
COMMITTEE


AIRCRAFT INCIDENT REPORT

PT Merpati Nusantara – Post Maintenance Test Flight

CN235 PK-MNM

Bandung, West Java

25 January 2000



NATIONAL TRANSPORTATION SAFETY COMMITTEE  
DEPARTMENT OF COMMUNICATIONS  
REPUBLIC OF INDONESIA  
2002

When the Committee makes recommendations as a result of its investigations or research, safety is its primary consideration. However, the Committee fully recognises that the implementation of recommendations arising from its investigations will in some cases incur a cost to the industry.

Readers should note that the information in NTSC reports is provided to promote aviation safety; in no case is it intended to imply blame or liability.

This report has been prepared based upon the investigation carried out by the National Transportation Safety Committee in accordance with Annex 13 to the Convention on International Civil Aviation, UU No.15/1992 and PP No. 3/2001.

This report was produced by the National Transportation Safety Committee (NTSC), Gd. Karsa Lt.2 Departemen Perhubungan dan Telekomunikasi, Jalan Medan Merdeka Barat 8 JKT 10110 Indonesia.

Readers are advised that the Committee investigates for the sole purpose of enhancing aviation safety. Consequently, Committee reports are confined to matters of safety significance and maybe misleading if used for any other purpose.

As NTSC believes that safety information is of greatest value if it is passed on for the use of others, readers are encouraged to copy or reprint for further distribution, acknowledging NTSC as the source.

# CONTENTS

<b>GLOSSARY OF ABBREVIATIONS</b>	<b>iii</b>
<b>SYNOPSIS</b>	<b>1</b>
<b>1 FACTUAL INFORMATIONS</b>	<b>2</b>
1.1 History of Flight	2
1.2 Injuries to Persons	2
1.3 Damage to Aircraft	2
1.4 Other Damage	3
1.5 Personnel Information	3
1.5.1 Cockpit Crew	3
1.5.1.1 Pilot-in-Command	3
1.5.1.2 First Officer	4
1.5.2 Airborne Mechanic	4
1.6 Aircraft Information	4
1.6.1 Aircraft Data	4
1.6.2 Engine Data	5
1.7 Meteorological Information	6
1.8 Aids to Navigation	6
1.9 Communications	6
1.10 Aerodrome Information	6
1.11 Flight Recorders	6
1.12 Wreckage and Impact Information	7
1.13 Medical and Pathological Information	7
1.14 Fire	7
1.15 Survival Aspects	7
1.16 Test and Research	7
1.16.1 Inspection of other CN235 aircraft	7
1.16.2 Metallurgical examination	8
1.16.3 Cabin depressurization test	8

<b>1.17</b>	<b>Organizational and Management Information</b>	<b>8</b>
1.17.1	PT Merpati Nusantara	8
1.17.2	PT Industri Pesawat Udara Nusantara	8
<b>1.18</b>	<b>Other Information</b>	<b>9</b>
<b>2</b>	<b>ANALYSIS</b>	<b>10</b>
2.1	Pressurization test	10
2.2	Material weakening	10
2.3	Ventral door detachment sequence	11
<b>3</b>	<b>FINDINGS AND CONCLUSIONS</b>	<b>12</b>
<b>4</b>	<b>RECOMMENDATIONS</b>	<b>12</b>
	<b>APPENDIX A - FIGURES AND PHOTOGRAPHS</b>	<b>A-1</b>

## GLOSSARY OF ABBREVIATIONS

<b>AD</b>	Airworthiness Directives
<b>AMSL</b>	Above Mean Sea Level
<b>AOC</b>	Air Operator Certificate
<b>ATC</b>	Air Traffic Control
<b>ATPL</b>	Air Transport Pilot License
<b>BDO</b>	Bandung
<b>CB</b>	Cumulonimbus clouds
<b>CSN</b>	Cycles Since New
<b>CVR</b>	Cockpit Voice Recorder
<b>DGAC</b>	Directorate General of Air Communication
<b>dp</b>	differential pressure
<b>FDR</b>	Flight Data Recorder
<b>ft</b>	feet
<b>GE</b>	General Electric
<b>IPTN</b>	Industri Pesawat Terbang Nusantara
<b>ITB</b>	Institut Teknologi Bandung
<b>km</b>	kilometer
<b>kts</b>	knots (nm/hr)
<b>LT</b>	Local Time
<b>nm</b>	nautical mile(s)
<b>NTSC</b>	National Transportation Safety Committee
<b>°C</b>	degrees Celcius
<b>PIC</b>	Pilot-In-Command
<b>psi</b>	pounds per square-inch
<b>QFE</b>	Height above airport elevation (or runway threshold elevation) based on local station pressure
<b>QNH</b>	Altitude above mean sea level based on local station pressure
<b>S/N</b>	Serial number
<b>TS/RA</b>	thunder strom and rain
<b>TSN</b>	Time Since New
<b>TT/TD</b>	ambient temperature/dew point
<b>USA</b>	United States of America
<b>UTC</b>	Universal Time Co-ordinated

## **SYNOPSIS**

On 25 January 2000, 03:00 LT, a CN235 aircraft owned and operated by PT Merpati Nusantara Airlines, with registration number PK-MNM, was flying a post maintenance test flight, when its ventral door detached and separated from the aircraft.

The aircraft took off from Husein Sastranegara airport, and was flying at 16,000 ft altitude, at radial 100 of VOR and 15 nm from the airport, and airspeed 150 kts, when the flight test crew heard a loud noise. The flight crew observed a depressurization with the differential pressure dropping to zero from 3.6 psi dp. Opening the cockpit door the crew found out that the ventral door had separated from the aircraft. The PIC initiated a rapid descent, returned to, and landed the aircraft safely at the airport. A ground search recovered the ventral door and other components in Majalaya, approximately 30 km south-east of Bandung.

Inspection on other CN235 aircraft was immediately performed and revealed corrosion occurring on most of the port fittings, hooks, reinforcements and their assemblies of the ventral door. Cabin pressurization test showed that cabin over-pressure did not occur, as the dump valve was working in accordance with the requirements. Metallurgical examination conducted at Institut Teknologi Bandung determined the cause of the failure of the port fittings as material weakening due to exfoliation and stress corrosion cracking. This was caused by insufficient protection coating measures for port fittings against adverse environmental condition.

Few recommendations were made as a result of this investigation, including recommendations for the DGAC, the manufacturer, and the operator.

# 1 FACTUAL INFORMATIONS

## 1.1 History of Flight

On 25 January 2000, the CN235 PK-MNM, owned by PT Merpati Nusantara, was scheduled for a post-maintenance flight test program. The aircraft has not been in service for 8 months prior to the maintenance. This test flight was performed as the aircraft was grounded for more than three months (stated in the company manual).

The crew performed a normal preflight briefing and check. There were no anomalies reported.

At 07:00 LT the crew started the engines, and after checking the propeller automatic and manual feathering systems, proceeded to take-off from Runway 29 at 07:10 LT. The aircraft was airborne at 07:15 LT, climbing to 10,000 ft heading to the planned test flight area approximately 15 nm from the Bandung Husein Sastranegara Airport. Weather was reported fine with scattered cumulonimbus formations over the airport.

The test program was initially conducted over the test area at 10,000 ft, but as the ATC transponder was not functioning properly and could not be read by Jakarta control, the flight crew requested to climb to 16,000 ft.

Five minutes after reaching 16,000 ft, while flying at a speed of 150 kts and heading of 100° on radial 100 about 15 nm from Bandung, the cockpit crew heard a loud noise, followed immediately by smoke and dust particles floating into the cockpit from the cabin area.

A loss of cabin pressure was recognized, and the cabin pressure indicated zero psi. The cockpit crew requested descent to 8,500 ft. An inspection of the cabin by the mechanic on board revealed that the ventral door had separated from the airframe tail section. Continuing the descent the PIC required the landing gear lowered.

On reaching 8,500 ft altitude, the crew requested and was cleared for a further descent to 4,500 ft. A further request to fly direct to Bandung Husein Sastranegara Airport for a long final on Runway 29, which was approved, and the aircraft landed safely at 08:15 LT.

On-ground inspection in a PT IPTN hangar revealed that the ventral door had separated at its hinges. A search successfully recovered the door at a position of 105° approximately 15 nm from Bandung.

## 1.2 Injuries to Persons

Injuries	Crew	Passengers	Others	TOTAL
Fatal	-	-	-	-
Serious	-	-	-	-
Minor/ None	3	-	-	3
TOTAL	<b>3</b>	-	-	<b>3</b>

## 1.3 Damage to Aircraft

The aircraft was inspected in a PT IPTN hangar at the Husein Sastranegara Airport, Bandung. The separated and detached parts included the ventral door, a cargo cage, a partition panel, 10 seatbelts and a fire extinguisher. The last three items were not recovered during a land search.

The examination of the aircraft, performed by an NTSC team supported by engineers from the DGAC, the operator and the manufacturer, revealed that thirteen fittings of the ventral door side frames were broken (Figure 1 and Photograph 1 B). Most of the fractures occurred along the grain direction. Other fractures showed static overload failures.

One of 14 hooks on the ventral door was found broken with its fracture surface indicating a static failure mode. The fracture surface indicated a static mode occurrence (Figure 1 and Photograph 2). Two hinge fittings and the ventral door attachment to the actuator at the rear frame were also broken statically (Photograph 3).

Frame # 43 in the rear fuselage to which the actuator was connected, was bent and partly torn (Photograph 4).

The skin panel lips of the fuselage opening were found deformed, with the deformation on the left hand side found larger than the deformations on the right hand side (Photograph 5). (Note: left and right hand referred to an observer looking in the direction of flight)

Other damaged and broken structure parts found separated were the baggage cage, which was bolted to the ramp door, and a partition panel. The baggage cage was recovered, while the partition panel was not found (Photograph 6).

## **1.4 Other Damage**

The two large parts, which separated from the aircraft, the ventral door and baggage cage, were found at Paseh village in Majalaya, approximately 30 km east of Bandung. The ventral door caused minor damage to the roof of a house, while the baggage cage did not cause any other damage. Both were found near each other, indicating that they had separated at about the same time.

## **1.5 Personnel Information**

### **1.5.1 Cockpit Crew**

#### **1.5.1.1 Pilot-in-Command**

<b>Age</b>	31 years
<b>License</b>	ATPL 3578
<b>Validation</b>	3 March 2000
<b>Aircraft ratings</b>	CN235
<b>Instrument rating</b>	Current
<b>Last medical check-up</b>	3 March 1999
<b>Last proficiency check</b>	25 August 1999
<b>Last line check</b>	None
<b>Flying experience (hours)</b>	DHC, CN235
<b>Total all types</b>	5889.47 hours
<b>Total on type</b>	3000 hours
<b>Last 90 days</b>	19.88 hours
<b>Last 72 hours</b>	6.00 hours
<b>Last 24 hours</b>	None
<b>This flight</b>	1.08 hours



### **1.5.1.2 First Officer**

<b>Age</b>	32 years
<b>License</b>	ATPL 8583
<b>Validation</b>	17 July 2000
<b>Aircraft ratings</b>	CN235
<b>Instrument rating</b>	Current
<b>Last medical check-up</b>	17 January 2000
<b>Last proficiency check</b>	4 September 1999
<b>Last line check</b>	None
<b>Flying experience</b>	DHC, CN235
<b>Total all types</b>	6838.58 hours
<b>Total on type</b>	3000 hours
<b>Last 90 days</b>	31.95 hours
<b>Last 72 hours</b>	None
<b>Last 24 hours</b>	None
<b>This flight</b>	1.08 hours

### **1.5.2 Airborne Mechanic**

<b>Age</b>	38 years
<b>License</b>	L 256
<b>Validation</b>	August 2000

## **1.6 Aircraft Information**

The last revenue flight of PK-MNM was from Palembang to Bandung on 9 October 1998. The aircraft was then proposed for heavy maintenance program (2000 hours inspection and some additional inspections), but due to the lack of spare parts such as avionics, brake units and electronics, the aircraft was grounded.

Later on after the completion of all components required, the aircraft was scheduled for test flight on 25 January 2000, which was the procedure for aircraft after more than 30 days not in service (refer to Company Operation Manual).

Last flight of the PK-MNM before the occurrence flight was to Bandung on 29 April 1999, with the PIC of the occurrence flight as pilot flying.

### **1.6.1 Aircraft Data**

<b>Aircraft registration</b>	PK-MNM
<b>Aircraft serial number</b>	N-012
<b>Aircraft manufacturer</b>	PT Industri Pesawat Terbang Nusantara
<b>Aircraft type / model</b>	CN235

<b>Year of manufacture</b>	1989
<b>Certificate of Airworthiness valid until</b>	22 April 2000
<b>Certificate of Registration valid until</b>	27 November 2002
<b>Registration number</b>	1436
<b>Weighing</b>	07 April 2002
<b>Compass swing</b>	08 April 2001
<b>Radio permit</b>	28 March 2000
<b>Completed date up to</b>	27 December 1999
<b>Total airframe hours</b>	5,914.20 hours
<b>Total cycles</b>	12,216 cycles
<b>Last major inspection</b>	C-03 / 5,912.28 hours
<b>Next major inspection</b>	C-04 / 7,912.28 hours
<b>Last minor inspection</b>	B-09 / 5,595.30 hours
<b>Next C-check FC05 inspection</b>	Not due yet
<b>Last heavy maintenance</b>	
<b>In</b>	MTA / BDO
<b>At hours / cycles</b>	5,912.28 / 12,216
<b>Date</b>	28 November 1998
<b>Next heavy maintenance (hours / cycles)</b>	7,912 / ----

### 1.6.2 Engine Data

	<b>#1</b>	<b>#2</b>
<b>Engine position</b>	GE, USA	GE, USA
<b>Engine manufacturer</b>	GE, USA	GE, USA
<b>Engine type</b>	GE-CT7-7A	GE-CT7-7A
<b>Engine serial number</b>	384128	384107
<b>Date of installation</b>	02-04-1998	15-04-1998
<b>Station</b>	MTA BDO	MTA BDO
<b>Installed at hours / cycles</b>	6,150 / 9,545	7,830 / 11,414
<b>Total TSN</b>	6,701.12	8,358.03
<b>Total CSN</b>	6,741	12,503
<b>Hours / cycles on wing</b>	550.91 / 1,196	527.77 / 1,089
<b>Cycle limits</b>	17,715	17,202
<b>Cycles remaining</b>	6,974	4,699

## 1.7 Meteorological Information

	0700 UTC	0800 UTC	0900 UTC
<b>Wind</b>	310 / 17	300 / 12	300 / 15
<b>Visibility</b>	4 km	6 km	2 km
<b>Weather</b>	TS / RA	Haze	TS / RA
<b>Clouds</b>	1 CB 3 Cm 1800	1 CB 3 Cm 1800	4 CB 1800
<b>TT / DP</b>	24 /20	24 / 19	23 /24
<b>QNH</b>	1011	1010	1012
<b>QFE</b>	926	925	926
<b>Remarks</b>	TS / RA	CB over Husein S	TS / RA over Husein S

## 1.8 Aids to Navigation

Not relevant.

## 1.9 Communications

Not relevant.

## 1.10 Aerodrome Information

Husein Sastranegara is situated in the southern part of Bandung, used as military, civil and industrial airport, operating under the Indonesian Civil Aviation Safety Regulations.

**Airport Name** : Husein Sastranegara

**Airport Identification** : WIIB

**Airport Operator** : PT Angkasa Pura II

**Runway Direction** : 29/11

**Elevation** : 2500 ft

## 1.11 Flight Recorders

The cockpit voice recorder was Fairchild cockpit voice recorder Model A100A S/N 53139. A transcript was made under supervision of the NTSC at the facilities of the PT Industri Pesawat Terbang Nusantara.

The flight data recorder was a Fairchild Digital Flight Recorder Model F800 S/N 3682 S/N but considered not necessary to be downloaded for read-out and analysis.

The CVR was transcribed at the PT IPTN read-out facilities. The recording revealed that the crew did not immediately recognize the cause of the ventral door detachment, and had

assumed the loud noise heard in flight was caused by a dump valve failure. The crew then observed indications of depressurization, i.e. the illumination of the 'cabin altitude' warning light, and a zero reading of the differential pressure indicator.

The crew started a descent immediately, but did not perform the correct procedure for this type of emergency. The crew did not put on their oxygen masks.

An in-flight inspection to check the cabin revealed that the ventral door was detached and had separated from the aircraft. The crew lowered the landing gears for an immediate landing descending with a high rate of descent, as the crew suffered some measure of ear-pain.

No emergency and normal checklists were performed, and the aircraft landed safely on Runway 29 Bandung Husein Sastranegara Airport.

The crew did not report the emergency to ATC.

## **1.12 Wreckage and Impact Information**

Two airframe components were separated from the aircraft, i.e. the ventral door and the baggage cage. The separation occurred in flight at an altitude of 16,000 ft. The ventral door was found at Desa Cipedes, Kecamatan Paseh, Majalaya, about 30 km east of Bandung. Both the ventral door and baggage cage hit two houses causing minor damage. They were found near to each other.

## **1.13 Medical and Pathological Information**

No one was injured in this accident, both in the air and on the ground. The detachment of the ventral door at 16,000 ft had caused a rapid depressurization, but the flight crew experienced no injuries even though they did not wear oxygen masks.

## **1.14 Fire**

Not relevant.

## **1.15 Survival Aspects**

The accident was survivable.

## **1.16 Test and Research**

### **1.16.1 Inspection of other CN235 aircraft**

For comparison purposes, visual inspections on 10 PT Merpati Nusantara CN235 aircraft were carried out. The inspection revealed corrosion occurring on most of the port fittings, hooks, reinforcements and their assemblies, some severely, especially corrosion of the reinforcements. The worst damage found showed similar characteristics to the PK-MNM case, where all the fourteen port fittings were corroded, of which eleven were showing severe exfoliation corrosion. Cracks along the grain directions were found in several of the fittings examined.

### **1.16.2 Metallurgical examination**

The Metallurgical Laboratory of the Mechanical Engineering Department, Institut Teknologi Bandung, conducted special tests. Utilizing a stereomicroscope the examination confirmed that the fracture was due to corrosion, more specifically of the exfoliation type, as shown by the fracture occurring along the grain direction, and revealing a fibrous wooden like surface. Corrosion that was white gray colored, were found on the fracture surfaces, and the formations of lamellar aluminum along the grain direction can be observed. These are characteristics of exfoliation and stress corrosion.

The laboratory examination could not determine the rate of corrosion crack propagation rate, or in other words, the time period in which the corrosion took place.

On several of the observed fracture surfaces reddish brown colored corrosion products from steel parts (i.e. brushing) were found, indicating penetration into the cracks or gaps formed by the exfoliation corrosion prior to the accident.

Static failure modes were found on several port fittings and the two hinge fittings at the rear of the aircraft. The static mode failures occurred after corrosion failures happened, ultimately causing a weakening the structure, until a static overload mode of failure occurred at the remaining fittings (Photographs 7 and 8).

### **1.16.3 Cabin depressurization test**

A dump valve taken from the PK-MNM aircraft was used for the depressurization test that was performed on the ground using a sister aircraft. The differential pressure at which the dump valve worked to open was found to be 3.9 Psi dp. This differential pressure met the set or prescribed value of  $3.8 \pm 0.1$  Psi dp.

## **1.17 Organizational and Management Information**

### **1.17.1 PT Merpati Nusantara**

PT Merpati Nusantara is a state owned Aviation Company operating under AOC/121-002, used for commercial and pioneer flights under CASR Part 121. The operator had 38 years of experience flying propeller aircraft and 10 years of flying gas turbine aircraft. It operates a total of 66 aircraft, including 3 B737s, 3 F100s, 16 F28s, 13 CN235s, CN212s and 8 de Havilland Otters. The company operated the CN235 since the early eighties, and has an in-house program for flight and cabin crew training. Total number of pilots is 639.

PT Merpati flies to 130 destinations in Indonesia.

The company does its own management at the Surabaya Merpati Maintenance Facilities.

### **1.17.2 PT Industri Pesawat Udara Nusantara**

The manufacturer of the aircraft is PT Industri Pesawat Terbang Nusantara, a government owned company. Established in 1976 the company, formerly PT Industri Pesawat Terbang Nurtanio, started manufacturing under license the Messerschmit-Boelkow-Blohm NBO105 helicopter and the CASA CN212 small utility transport under license from CASA of Spain. These programs were quickly followed by the license manufacturing of the PUMA NSA-330 (manufacturer Aero-Spatiale of France) and the SUPER PUMA. The next program was the CN235 program a joint risk sharing development between CASA and PT IPTN. The CN235 first flight was in December 1983, three years after the start of the program, and the certification process was successfully ended in 1986. The aircraft sales until now are around 160 aircraft flying all over the world. In the early eighties PT IPTN manufactured components for the Boeing 767 and 737, and the General Dynamics F16, as offset production lines. It also manufactured the Bell-412 under license. The next program in the late eighties was the design and manufacturing of the N250, a turbo-propeller aircraft,

which is a pure national program. Finally the design of the N2130 has begun in the early nineties. The PT IPTN is recently renamed PT Dirgantara Indonesia.

PT IPTN conducted the heavy maintenance on PK-MNM.

### **1.18 Other Information**

None.

## 2 ANALYSIS

### 2.1 Pressurization test

The pressurization test showed that the dump valve worked to open at 3.9 Psi dp. This value met the requirements. Therefore the possibility of cabin over-pressure can be ruled out.

### 2.2 Material weakening

A detailed inspection was carried out at the Metallurgical Laboratory of the Mechanical Engineering Department of the ITB. A stereomicroscope was used in the examination that confirmed that the fracture was due to corrosion, more specifically of the exfoliation type. This was concluded as it can be observed that the fracture occurred along the grain direction, and the fracture revealed a fibrous (wooden like) surface. White-gray colored corrosion products were found on the fracture surfaces, and the formations of lamellar aluminum along the grain direction were observed. This type of corrosion is known as exfoliation and stress corrosion.

The laboratory examination could not conclude on the rate of corrosion crack propagation rate, or in other words, the time period in which the corrosion took place.

On several of the observed fracture surfaces reddish brown colored corrosion products from steel parts (i.e. brushing) were found, indicating penetration into the cracks or gaps formed by the exfoliation corrosion prior to the accident.

Static failure modes were found on several port fittings, and the two hinge fittings at the rear of the aircraft. The static mode failures occurred after corrosion failures happened, ultimately causing a weakening of the structure, until a static overload mode of failure occurred at the remaining fittings (figures 7 and 8).

The examination also found that 13 of the 14 fittings of the ventral door were broken.

An analysis of the results of the metallurgical laboratory examination concluded that most of the port fittings experienced corrosion in the form of exfoliation and stress corrosion. The corrosion started when corrosive environment, e.g. moisture, was in contact with the aluminum. One of the protective methods is to separate them from having a direct contact with corrosive environment. In the case of the port fittings, the coating used was an anodized layer and primer coating. During an anodization process, a thin layer of aluminum oxide ( $\text{Al}_2\text{O}_3$ ) is formed on the surface. However the layer does not continuously cover the metal surface, due to micro-porosity. In order to close the porosity, the part is immediately immersed in a bath of hot water directly after the anodization process. In this immersion, the layer transforms into  $\text{Al}_2\text{O} \cdot n\text{H}_2\text{O}$ , which has a larger volume than  $\text{Al}_2\text{O}_3$ , and hence the porosity will be sealed off. On the top of the anodized layer, a coating of primer is applied to prevent the moisture from contacting the metal.

It was found that from the part drawing and manufacturing processing specifications, on these particular port fittings the anodization process was not followed by a sealing step, that is a protection especially needed in hot, humid and maritime type of environment. If there is no such protection, surface corrosion will be initiated. This is followed by exfoliation corrosion, which is typical of high strength aluminum. The grain boundaries will be severely attacked. In a rolled or extruded products, the weakening will occur along the elongated grains. In the extreme stage it will form loose layers of exfoliation.

Another form of corrosion is stress corrosion cracking. The presence of tensile stress in the parts working in corrosive environment will accelerate the corrosion progress. The cracks

will form along the weakened grain boundaries. This form of corrosion was observed in the port fittings.

These facts indicate that the protection measures were not sufficient to the particular work environment. This is also supported by the fact that a higher number of corroded fittings were observed in other aircraft, which were also grounded for longer periods of time in hot, humid or maritime environments.

### **2.3 Ventral door detachment sequence**

The nature of fractures of the port fittings and rear hinges, and the deformation of the fuselage lips, indicated that there was a weakening of the several port fittings. The normal pressurization caused the left of the ventral door to detach, starting from the left-hand side. This was indicated by the greater deformation observed on the left side fuselage lip or edge panel.

Additional aerodynamic loads were exerted on the protruding ventral door, causing failures of the remaining fittings, included the two hinge fittings at the rear. The aerodynamic drag pulling resulted in the failure of the actuator attachment on the door, as well as bend tear fractures on fuselage frame #43. The right hand fittings were broken, starting at the corroded ones. Depressurization forces, i.e. air rushing from inside the aircraft then caused the baggage compartment and one of the partition walls to be pushed out through the ventral door opening.



### **3 FINDINGS AND CONCLUSIONS**

- 1) The cause of the ventral door detachment was failure due to a weakening of port fittings caused by exfoliation corrosion and stress corrosion cracking. This was caused by insufficient protection coating measures for port fittings against adverse environmental condition.
- 2) There is no non-destructive-testing inspection to check for corrosion effects on the ventral door hinges, especially for hinges on the most rear position due to limited accessibility. The inspection can only be done visually, which is not enough to do a thorough check.
- 3) The crew did not perform a specific pre-test flight briefing.
- 4) The flight crew did not comply with flight procedures for descent and landing.
- 5) There were indications of insufficient compliance to the CRM processes and procedures by the flight crew.
- 6) The crew did not inform ATC of the flight emergency situation.


### **4 RECOMMENDATIONS**

- 1) The Directorate General of Air Communication to issue a directive to inspect port fittings and related parts of all CN235 aircraft flying in Indonesia by means of appropriate techniques.
- 2) The manufacturer to perform a review on the structural significant items, especially on:
  - a. Corrosion control program. An additional corrosion protection process immediately after anodization step is strongly recommended (this measure has been applied to the fittings since 1993). The application of an additional coating containing primer, top coat and corrosion inhibiting compound (CIC) is also recommended on particular parts that can potentially be attacked by corrosion.
  - b. Material selection. It is recommended that Al2024, instead of Al7075, be used for the hinges.
  - c. Manufacturing process. It is recommended to take into consideration the grain direction relative to the load in the manufacturing of the hinges.
- 3) The Directorate General of Air Communications to notify operators and air safety authorities worldwide on the incident and its cause.
- 4) The operator to review and enforce the high altitude emergency procedures.
- 5) The operator and the manufacturer to provide standard flight test procedures, including ground acceptance procedures outlining the flight test details and its specific procedures.
- 6) The operator to review its accident/incident notification procedure according to the company operation manual.

## **APPENDICES**

### **Appendix A - FIGURES AND PHOTOGRAPHS**

**"CORROSION FINDING REPORT" PADA VENTRAL DOOR (PK-MNMW/NI2)**



**Figure 1. Corrosion Finding at Ventral Door.**



**Photograph 1A. One Remaining Unbroken Fitting**



**Figure 1B. Broken Fitting on Ventral Door Structure (13 fittings)**




**Photograph 2. Broken Guide Hook (R4)**




**Photograph 3. Broken Hinge and Half Hinge Assembly**



**Photograph 4. Bend and Tear out on Upper Frame #43**




**Photograph 5. Deformation on Rear Fuselage Skin Panel Lips (left-hand side)**



**Photograph 6. Baggage Basket (Compartment)**



**Photograph 7. Macroscopic Photograph on L7 Port Fitting Fracture Surface**



**Photograph 8. Macroscopic Photograph on R5 Port Fitting Fracture Surface**